

TAMCO
12459-B Arrow Route
Rancho Cucamonga, CA
91739

Prepared by:

Yorke
ENGINEERING, LLC
www.YorkeEngr.com

31726 Rancho Viejo Rd., Ste. 218
San Juan Capistrano, CA 92675
(949) 248-8490

2013 Annual Report

received
5011 3/6/2014

2013 Annual Report for Hazardous Waste Exports

**40CFR § 262.56
Title 22 CCR §66262.56**

Prepared for:

Jeff Dambrun
Environmental Manager
TAMCO
12459-B Arrow Route
Rancho Cucamonga, CA 91739

February 2014

Table of Contents

1.0	Exporter Information.....	1
1.1	EPA Identification Number.....	1
1.2	Facility Name.....	1
1.3	Mailing Address:.....	1
1.4	Site Address:	1
2.0	Calendar Year of Report.....	1
3.0	Consignee Information	2
3.1	EPA Identification Number.....	2
3.2	Facility Name.....	2
3.3	Mailing Address:.....	2
3.4	Site Address:	2
4.0	Hazardous Waste Information	2
4.1	Description	2
4.2	EPA Hazardous Waste Number.....	2
4.3	California Hazardous Waste Code.....	2
4.4	DOT Hazard Class.....	2
4.5	Transporter Information	2
4.5.1	<i>Burlington Northern Santa Fe Railway Company.....</i>	<i>2</i>
4.5.2	<i>Kansas City Southern Railroad</i>	<i>3</i>
4.5.3	<i>Kansas City Southern Mexican Railway Company</i>	<i>3</i>
4.6	Waste Shipments:	3
5.0	Waste reduction efforts.....	3
5.1	Efforts Undertaken to Reduce the Volume and Toxicity of Waste.....	3
5.1.1	<i>Reduction in Volume</i>	<i>3</i>
5.1.2	<i>Reduction in Toxicity</i>	<i>4</i>
5.2	Description of Changes in the Volume and Toxicity of Waste Actually Achieved During the Year in Comparison to the Extent Such Information is Available for Years Prior to 1984.....	4
6.0	Certification by Exporter	4

1.0 EXPORTER INFORMATION

TAMCO is a steel mini-mill that recycles ferrous scrap metal into concrete reinforcing bars (rebar). Mini-mills use electric arc furnace technology to melt scrap steel into semi-finished steel billets. These billets are then reheated and processed in a rolling mill where they are made into a wide variety of rebar lengths, sizes and grades.

TAMCO recycles over 500,000 tons of steel a year. This steel comes from junked cars, appliances, tin cans, and industrial scrap. More steel is recycled in the United States than glass, aluminum, paper and plastic combined.

TAMCO captures dust emissions from the melting process with an efficient baghouse, thus keeping the dust from entering the atmosphere. Once the dust is captured, the iron, zinc, lead and cadmium in the dust is recycled, which reduces the amount of material that goes to hazardous waste landfills.

1.1 EPA Identification Number

CAD982361404

1.2 Facility Name

TAMCO

1.3 Mailing Address:

P.O. Box 325

Rancho Cucamonga, CA 91739

1.4 Site Address:

12459-B Arrow Route

Rancho Cucamonga, CA 91739

2.0 CALENDAR YEAR OF REPORT

2013 and revised totals for 2012.

3.0 CONSIGNEE INFORMATION

3.1 EPA Identification Number

TXR000047670

3.2 Facility Name

Zinc Nacional S. A.

3.3 Mailing Address:

c/o VDC Corporation

3104 Chelo Street & Highway 57

Eagle Pass, TX 78852

3.4 Site Address:

Serafin Pena, 938 Sur

Monterrey, Nueva Leon, Mexico

4.0 HAZARDOUS WASTE INFORMATION

4.1 Description

Baghouse dust captured from the process of recycling steel with an electric arc-furnace.

4.2 EPA Federal Hazardous Waste Code

K061 - Emission control dust/sludge from the primary production of steel in electric furnaces

4.3 California Hazardous Waste Code

591 - Baghouse waste

4.4 DOT Hazard Class

DOT Hazard Class 9 – Miscellaneous

4.5 Transporter Information

4.5.1 Burlington Northern Santa Fe Railway Company

3001 Lou Menk Drive

Forth Worth, TX 76131-2815

EPA ID Number: MND048341788

ATTN: David Rodriguez

4.5.2 Kansas City Southern Railroad

1610 Woodstead Court

The Woodlands, TX 77380

EPA ID Number: NOD006965859

4.5.3 Kansas City Southern Mexican Railway Company

Monterrey, México

Kansas City Southern de Mexico, S.A. de C.V.

Manuel L. Barragán No. 4850 Nte.

Col. Hidalgo

C.P. 64420

EPA ID Number: None

4.6 Waste Shipments:

For calendar year 2013, baghouse waste export shipments were 8,981,020 pounds (4,490.51 tons) in a total of 48 shipments.

For calendar year 2012, baghouse waste export shipments were 8,426,280 pounds (4,213.14 tons) in a total of 45 shipments. This revision corrects two shipments made in 2013 that were inadvertently included in the 2012 totals.

Table 1 - Annual Waste Exported

Year	Pounds of Baghouse Dust Exported
2012	8,426,280
2013	8,981,020

5.0 WASTE REDUCTION EFFORTS

5.1 Efforts Undertaken to Reduce the Volume and Toxicity of Waste

5.1.1 Reduction in Volume

Manufacturing steel from recycled steel represents a significant reduction in waste. Annual steel recovery efficiency average is 98.6%. Waste shipments are for additional recycling by metal recovery which continues to represent additional waste volume reductions.

5.1.2 Reduction in Toxicity

Inspections of incoming recycled steel continue at the facility preventing the introduction of unwanted materials. No changes can be expected in the Toxicity Characteristics of the baghouse dust.

5.2 Description of Changes in the Volume and Toxicity of Waste Actually Achieved During the Year in Comparison to the Extent Such Information is Available for Years Prior to 1984.

Data is not available in years prior to 1984. Current recovery efficiency is stable at an average of 98.6% for the last eight years.


Table 2 - Annual Recycle Rate

Year	Pounds of Baghouse Dust	Pounds Produced	Recycle Rate %
2006	14,566,200	1,002,040,000	98.6%
2007	12,720,400	861,392,000	98.5%
2008	14,680,000	886,964,000	98.4%
2009	3,751,600	276,996,000	98.7%
2010	6,096,950	436,988,000	98.6%
2011	6,780,250	409,860,000	98.6%
2012	9,513,530*	671,750,000	98.6%
2013	8,981,020	584,906,000	98.5%
Average			98.6%

**2012 Pounds of Baghouse Dust for Recycle Rate calculation includes shipments to domestic locations.*

6.0 CERTIFICATION BY EXPORTER

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.



Mr. James Crompton
VP/General Manager



UNITED STATES POSTAL SERVICE

TAMCO
P.O. Box 325
RANCHO CUCAMONGA, CA
Flat Rate Mailing Envelope 91739

Visit us at usps.com

Route EPA Mail

International Compliance
Assurance Division

Stop ARIEL RIOS NORTH

artment: 2254A


ified



7011350000214897169

RETURN RECEIPT
REQUESTED

8/28




7011 3500 0002 1489 7169

RETURN RECEIPT
REQUESTED



1006

20460



RANC

OFFICE OF ENFORCEMENT and COMPLIANCE
OFFICE of FEDERAL ACTIVITIES
INTERNATIONAL COMPLIANCE ASSURANCE
DIVISION (2254 A)
ENVIRONMENTAL PROTECTION AGENCY
1200 PENNSYLVANIA AVE, NW
WASHINGTON DC. 20460